

U.S. Senate

Desk Description and Condition Report

Desk No : **66.00044.000**

Paper Label No.(on shelf bottom): 87

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 87, 89, XLIV / Top: (stamped) 87.
(Pencil) 81, "Cranston Calif." / Drawer Bottom: outside -; inside - /Drawer Back: (pencil) 87 / Bottom of
Shelf (other than paper label): / Drawer Blade: / Inside Case Back: / Inkwell:

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 1/4	32 1/4		
Width (front)	27 5/8	26 1/2	25 3/4	
Width (rear)	27 1/8	26	25 1/8	
Depth	20 1/4	19 1/2	19 1/8	9 1/8

* Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Primary:

Mahogany ☒

Mahogany veneer ☒

Rosewood veneer ☐

Other Wood (specify): _____

Character of case mahogany:

Plain ☐

Ribbon ☒

Mottled ☐

Crotch ☐

Other ☐

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides			✓		
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior	✓		✓		
Drawer Front	✓				

Construction Details

Leg:

Wood Type	rosewood crossband	other crossband	no crossband
mahog. veneer			
solid mahogany			✓
other: _____			

Foot construction: 1-part ☒
 2-part ☐
 5-part ☐
 Other: _____

Cockbead width on bottom of drawer front:
 Narrow ☐
 Full width ☒

Double bead on edge of leg:
 Bead: Thick ☐
 Thin ☒
 Leg Thickness: 1"

Opening in original top for inkwell: Yes ☐
 No ☒

Roundels: Single piece ("yo-yo" form) ☐
 Applied boss ☒

Shape of cross-stretcher edges:
 Rounded ☐
 Rectangular ☒

Inset distance of single bead on desk back panel:
 Side: 1 1/4"
 Top: 7/8"
 Bottom: 7/8"

Spindle type:	Thick	Thin	Other
Number		10	

Joinery of lower drawer blade to case sides:
 single dovetail ☐
 2 dovetails ☐
 3 dovetails ☐
 lap joint ☐
 other: full width is obscured

No. of Glue Blocks	Case	Stretch'r	Shelf
Original/Old			
New/Recent			2
Missing			

Shelf molding applied: Yes ☐
 No ☒

Interior case-side flush with corner block? Yes ☐
 No ☒

Width of drawer-opening offset Right: 1/2"
 Left: 1/2"

Condition of Desk

Structure

Previous breaks in structural elements: Yes ☐
(shown on schematic)
No ☒

Current split or broken elements: Yes ☒
(shown on schematic)
No ☐

Other loose or damaged joinery: Yes ☐
(describe in narrative)
No ☒

Damage to drawer front: Extreme ☐
Moderate ☒
Minor ☐

Drawer lock: relocated on face Yes ☒

Drawer lock: resized on inside Yes ☒

Cockbead on drawer front: Damaged ☒
(show on schematic)
Missing ☐
Loose ☐
Replacements ☒

Replaced drawer-side runners: Yes ☒
No ☐

Replaced case-side runners: Yes ☒
No ☐

Drawer bottom pieced-out at back edge: Yes ☐
No ☐

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 0

Number of replaced spindles: (show on schematic) No: 1

Replaced veneers and cross-banding: Yes ☐
(show on schematic)
No ☒

Missing veneers and cross-banding: Yes ☐
(show on schematic)
No ☒

Delaminated/loose veneers & cross-banding: Yes ☐
(show on schematic)
No ☒

Shelf supports: Original/old ☐
New/recent ☒
Missing ☐

Spindle support board in case: Yes ☐
No ☒

Finish

Age	Excellent	Good	Fair	Poor
New		✓		
Old			✓	
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)			
Knob (R)			

Toe cap size:

Right toe: 9

Left toe: 9